

October 20, 1949

Police Department
County Building
Silver Spring, Maryland

Gentlemen:

At a recent meeting of the Park Hills Civic Association there was considerable discussion about the dangerous condition which exists at the student loading area on the corner of Dale Drive and Wayne Avenue. This is brought about mainly by the fact that cars tend to cut inside of the stop sign and cross over the loading zone before driving onto Dale Drive. This may be due in part to the fact that there is no demarcation between the surface of the road and the surface of the loading zone.

There are perhaps several ways of improving the safety at this particular area but those in attendance at the meeting felt that it would be advisable to have a line painted from the present stop sign along the edge of Wayne Avenue, the entire width of the loading zone and at the far end of the line to erect a sign instructing motorists not to cross this line. In view of your extensive experience in matters of this type, I am sure you may think of additional ways that may prevent possible accidents to our students. Any additional precautions you take will be greatly appreciated by our group.

Sincerely yours,

B. R. Stanerson
Secretary

BRS:atw

cc: Mr. D. B. Johannes, Jr.